



- High Precision Digital Test Gauges: up to ±0.02% of measured value
- Versions: Industrial and "intrinsic safety"
- Ambient temperature: -20...60 °C
- Ingress protection rating: IP65 or IP54
- Integrated 5-segment LCD screen with backlight and graphical display
- Wide range of units: Pa, kPa, Mpa, kgf/cm², kgf/m², mm Hg, bar, psi
- 0° to 340° rotatable body

### Stand-alone Mode for Field Measurements

In the stand-alone mode device is powered by its integrated battery. This mode enables the PDE-020I, PDE-020IEx models to be used in industrial environment and in the field, for process monitoring and to check shop instruments on site.

# EX CE

DE-020IFx

### **Comprehensive Screen**

Measured pressure values are indicated on a 5-segment digital screen with a bar indicator and backlight. There is a field to indicate the battery status or the relative value expressed as percentage of the upper span limit. The screen also displays the current unit of measurement (Pa, kPa, MPa, kgf/cm², kgf/m², mm Hg, bar, psi).

#### **Application**

Digital test gauges PDE are used for testing process pressure measurements, and for calibration and verification of shop instruments in lab, industrial, and field environment.

The PDEs provide high-precision absolute and manometric fluid pressure and gas expansion pressure measurements.

It can be used as calibrator components for pressure gauge and pressure transducer adjustment, calibration, and verification in the field. They also serve as a high-precision (reference) pressure measuring instrument.

### **Basic Specifications**

PDE	020	020I	020IEx
Body	Stainless steel	Impact-resistant plastic, wear-resistant rubber, stainless steel	Aluminum, wear resistant rubber, stainless steel
Rotatable body	_	03	40°
Display	_	LCD, with backlight	
Battery	_	Li-Ion	NiMh
Pressure measurement error	<ul> <li>up to ±0.02 % (A0 order code)</li> <li>up to ±0.03 % (A order code)</li> <li>up to ±0.05 % (B order code)</li> <li>up to ±0.1 % (C order code)</li> </ul>		
Output interface	RS-232 (USB)		
Compatible	IKSU-2012, KDM-030, PKD-260		
multifunctional calibration systems	KDM-020		

### Easy to Use

You do not need a menu to control the PDE: all the functions are button-controlled. The 5-button keypad on the front panel lets you switch the instrument on and off, select a unit of measurement, turn the backlight on/off, adjust zero, and view the max measured value. It takes just a couple of minutes to learn. Just open the box and you are ready to proceed!

#### **Overload Protection**

The PDEs have a buzzer to give an audible overpressure warning. The warning threshold is adjustable from a PC.

# **Impact-Resistant Body**

The PDE body is made of impact-resistant plastic or metal. PDE-020I and PDE-020IEx bodies are rubber coved for extra protection.

# Universal Digital I/O

To enable PC-controlled calibration and adjustments, and to operate as part of the IKSU-2012 Multifunctional Calibration System and of the PKD-260, KDM-020 (030) Pressure Calibrators, the PDEs are equipped with a digital data link and an RS-232 interface (a USB converter to connect to PC).

# PDE-020(Ex), PDE-020I(Ex) Specifications



# **Basic Specifications**

	PDE-020(Ex)	PDE-020I	PDE-020IEx	
Feature	The state of the s	PDE-0201 ©	CE C	
Screen	_	LCD, 5-segmen	t, with backlight	
Keypad	_	— Membrane		
Max weight, kg	0,2	0,4	0,8	
Dimensions, mm	106 × 27 ×31	153 × 94 × 37	$207 \times 119 \times 68,5$	
Battery	_	Li-Ion	NiMh	
Ambient conditions	−20+60 °C			
Humidity	RH 095 %			
Measurement rate	100 ms			
Data update rate	300 ms			
Ingress protection rating	IP54	IP54 IP65		

# **PDE Models**

Model	Pressure measured	Pressure range	Max pressure	Order code
010	Absolute	010 kPa	150 kPa	В, С
030	Absolute	0120 kPa	300 kPa	A0, A, B, C
040	Absolute	0250 kPa	1 MPa	A0, A, B, C
050	Absolute	0600 kPa	2 MPa	A0, A, B, C
060	Absolute	02,5 MPa	6 MPa	A0, A, B, C
070	Absolute	06 MPa	16 MPa	A0, A, B, C
080	Absolute	016 MPa	25 MPa	A0, A, B, C
110	Manometric	06,3 kPa	100 kPa	A, B, C
120	Manometric	016 kPa	100 kPa	A0, A, B, C
120E	Manometric	040 kPa	200 kPa	A0, A, B, C
130	Manometric	0100 kPa	300 kPa	A0, A, B, C
140	Manometric	0250 kPa	1 MPa	A0, A, B, C
150	Manometric	0600 kPa	1,6 MPa	A0, A, B, C
160	Manometric	02,5 MPa	6 MPa	A0, A, B, C
170	Manometric	06,0 MPa	16 MPa	A0, A, B, C
180	Manometric	016 MPa	25 MPa	A0, A, B, C
190	Manometric	060 MPa	100 MPa	A0, A, B, C
190E	Manometric	0100 MPa	120 MPa	A0, A, B, C
310	Manometric negative pressure	−1010 kPa	100 kPa	A, B, C
320	Manometric negative pressure	-4040 kPa	200 kPa	A0, A, B, C
340	Manometric negative pressure	−100160 kPa	1 MPa	A0, A, B, C
350	Manometric negative pressure	−100600 kPa	1,6 MPa	A0, A, B, C

## **Basic accuracy**

Order code	Range	Accuracy, δ
A0	up to 50 % upper limit	±0.01 % of upper limit
	from 50 to 100 % upper limit	±0.02 % of measured value
۸	up to 33 % upper limit	±0.01 % of upper limit
Α	from 33 to 100 % upper limit	±0.03 % of measured value
D	up to 33 % upper limit	±0.017 % of upper limit
В	from 33 to 100 % upper limit	±0.05 % of measured value
С	up to 33 % upper limit	±0.033 % of upper limit
	from 33 to 100 % upper limit	±0.1 % of measured value

# **Complementary error**

Complementary error caused by	Value
Air pressure change by $\pm 10$ kPa (75 mm Hg) from the steady value in the 84106.7 kPa (630800 mm Hg)	max 0,2 δ
Ambient temperature change from the normal one (23 $\pm$ 2) °C to any other value within the operating temperature range per each 10 °C temperature change	max 0,5 δ

 $\delta$  — is the basic accuracy



**PDE-0201Ex** as part of the PKD-260 Portable Pressure Calibrator



**KDM-020Ex** with a PDE-020Ex connected



**PDE-020I** as part of the IKSU-2012 Multifunctional Calibration System



**KDM-030Ex** with a PDE-020IEx connected

